Work Orde Wednesday, Sept												Page 1
Item ID: Revision ID:	D3564-13			Accept				iii s	etup S	Start		
Item Name:	Wearshoe								:	Stop		
Start Date:	9/22/2010	<b>Start Qty:</b> 12.00			Cust Item I	D:						
Required Date: Reference:	9/29/2010	Req'd Qty: 12.00			Customer:	Ş				•		
Approvals:	Process Plan	n: <i>M</i>	Date: 6-9-27	Tooling:	Di	ate:		R	tun S	Start		
	QC:	//	Date:	SPC (Y/N):		ate:			:	Stop		
Sequence ID/ Work Center ID		Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty		Reject Number	Insp. Stamp
Draw Nbr	Revi	sion Nbr										
D3564	Rev 1	D										
100    <b>                                 </b>		FLOW WATER JET		0.00				fQ (c	D~ 9~	- 28		
Waterjet FLOW CNC Waterje 304.	.ce3	Memo 1-Cut as per Deburr if ne	Dwg D3564 □Dwg Rev:_ccessary	0.00 □Prog Rev:_	□2-						(	9
110		QC2- Inspect parts off m	nachine FAI/FAIB	0.00								
QC Quality Control		Memo		0.00				18	0-9-	- >8 -	<u> </u>	
120		QC8- Inspect parts - seco	and check	0.00	. 1							
QC Quality Control		Memo		<sub>0.00</sub> O G	०१०२।२५०			(+12)	·		<del></del>	

W/O:	•		V	VORK (	ORDER CHA	ANGES								
DATE	STEP	PRO	CEDURE CI				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
						,								
Part No	•	PAR #:	Fault Ca	itegory: _		NC	R: Yes	No <b>DQ</b>	A:	Date: _				
		esolution:												
NCR:		V	WORK ORDER NON-CONFORMANCE (NCR)											
DATE	STEP	Description of NC			Section B	T Gian 9		cation	Approval	Approval				
<i></i>	J.L.	Section A	Initial Chief Eng	-	Chief Eng		Sign 8 Date	Secti	on C	Chief Eng	QC Inspector			
		,				•								
											٦			
	:													
				. 1,										

#### Work Order ID 62229

Wednesday, September 22, 2010 3:16:19 PM



Page 2

Item ID:

D3564-13

Accept



Setup Start



**Revision ID:** 

Item Name:

Wearshoe

Start Date: 9/22/2010 Required Date: 9/29/2010 **Start Qty: 12.00** 

Req'd Qty: 12.00

**Cust Item ID: Customer:** 

Reference:

Approvals:

Process Plan: \_\_\_\_\_

Date:

Tooling:

Date:

Date:

Run

Qty

Start Stop

Stop



Date:

**SPC (Y/N):** 

Set Up/

**Run Hours** 

**Tool ID** 

bl 10-9-30

Tool # Plan

Code

Accept Otv

Reject Reject Number

Insp. Stamp

Sequence ID/ **Work Center ID** 

130

Brake NC Brake NC

Operation Description

NC BRAKE

Memo

0.00

0.00

Deburr if necessary | Form on Brake as per Dwg D3564 using Jigs DT 8179 io | 9 |

140

QC

Quality Control

QC5- Inspect part completeness to step on W/O

0.00

Memo

0.00

150

Powdercoat

Powder Coating

Grey Sandtex(Ref: 4.3.5.6) per QSI005 4.3

Memo

0.00

OOVEN TEMPERATURE:

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					. ]				
Part No	:	PAR #:			_ NCR: Yes	No <b>DQ</b>	A:	_ Date: _	
	Re	esolution:	Dispositi	on:	_ QA: N/C C	losed:		Date: _	
NCR:			WORK OR	DER NON-CONFORMA	ANCE (NCI	₹)			
DATE	STEP	Description of NC		ion B	Verifi		Approval	Approval	
DAIL	SIEF	Section A	` Initial Chief Eng	Action Description Chief Eng	Sign Date		tion C	Chief Eng	QC Inspector
								ļ	-

Page 3

Item ID:

D3564-13

Wednesday, September 22, 2010 3:16:19 PM

Accept

Setup Start

Stop



**Revision ID:** 

**Start Date:** 

Item Name: Wearshoe

**Required Date: 9/29/2010** 

9/22/2010 Start Qty: 12.00

**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Tool ID

Run Start



Date:\_\_\_\_\_

SPC (Y/N):

Date:

Stop

Sequence ID/ Work Center ID

160

**Quality Control** 

Operation Description

QC3- Inspect Part Finish

Req'd Qty: 12.00

Memo

Set Up/ **Run Hours** 

10/09/30

Tool # Plan Code Qty

Accept Reject Qty

Reject Insp. Number Stamp

170

Packaging Packaging

Identify as per dwg & Stock Location: FR-16 0.00 BL 10-9-30

Memo

0.00

180

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/10/01981 WF10-9-30

Dart Ae	rospace L	.td						g
W/O:			WC	RK ORDER CHANGES				
DATE	STEP	PROCEDURE CHANGE			Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							;	
Part No	•	PAR #:	Fault Cate	gory: N	CR: Yes N	lo DQA:	Date: _	
	Res	olution:	Disposition	n: Q	A: N/C Clo	sed:	Date: _	
NCR:			WORK ORD	ER NON-CONFORMANC	E (NCR)			
D.4.T.E	0	Description of NC		Corrective Action Section B			Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Chief Eng	QC Inspector

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification	Verification Approval	Approval			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspector			
			:	•							
		·									
							}				

#### **Picklist Print**

Wednesday, September 22, 2010 3:16:23 PM

Work Order ID: 62229

Parent Item: D3564-13

Parent Item Name: Wearshoe

**Start Date:** 9/22/2010

Required Date: 9/29/2010

**Start Qty: 12.00** 

Required Qty: 12.00

Comments:

IPP Rev:A

New Issue 07-03-08 ec

IPP Rev:B

As per Rev C 07-07-09 JLM -

IPP Rev:C

As per Rev D 07-09-09 JLM Verified By:EC

IPP Rev:D Comments revised on Step 5, 6 per B44657 09-02-04 KJ

Verified By:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304S16GA	ANNEL ANDRE HOL PROE	Purchased	No			100	sf	160.8400	0.222	2.804211		18.1	
							•			i <b>S</b> i	510-9-	>8	

304/316 Sheet .063

Location		Loc Oty	Loc Code	
MAT		146.7		
	111323	0		
	115688	146.7		115689
MAT20		14.14		
	115440	14.14		



									· · · · · · · · · · · · · · · · · · ·
W/O:			WC	RK ORDER CHANG	ES				
DATE	STEP	PRO	CEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		~-							
	<u> </u>								
Part No	):	PAR #:	Fault Cate	jory:	_ NCR: Yes	No DQA	·	_ Date: _	
	R	esolution:	Disposition	1:	_ QA: N/C Cld	osed:		Date: _	
NCR:		V	WORK ORDE	R NON-CONFORM	ANCE (NCR	)			
		Description of NC	Corrective Action				ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	'QC Inspector
							· // · · · · · · · · · · · · · · · · ·		
								Ì	

DART AEROSPACE LTD	Work Order:	62229
Description: Wearshoe	Part Number:	D3564-13
Inspection Dwg: D3564 Rev: D		Page 1 of 1

### FIRST ARTICLE INSPECTION CHECKLIST


Х	First Article		Prototype
---	---------------	--	-----------

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
7.00	+/-0.030	7,000	8		V Box	
2.432	+/-0.010	2.439	٧		ν	
3.227	+/-0.010	3.223	25		ν	_
3.500	+/-0.010	3,499	7		V	
0.300 x 0.300	+/-0.010	305 X305	'A		ν	
Ø0.188	+0.005/-0.001	(191	<b>%</b>		V	
0.063	+/-0.010	,060	8		V	
					,	
	· · · · · · · · · · · · · · · · · · ·					
						•

Measured by:	iB	Audited by:	Prototype Approval:	N/A
Date:	10-9-28	Date: 10/09/08	Date:	N/A


Rev	Date	Change	Revised by Approv	ved
Α	07.04.02	New Issue	KJ/JLM	
В	07.07.18	Dimensions updated per Dwg Rev. C	KJ/JLM	
С	08.02.28	Dwg Rev updated	KJ/DD 🖟	

W/O:		WORK ORDER CHANGES											
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
								ļ					
Part No:		PAR #:	Fault Categ	NCR: Yes No			lo DQA: Date:						
Resolution:		Disposition:			QA: N/C Closed: Date:								
NCR:			WORK ORDE	R NON-CONFORM	ANCE	(NCR)							
DATE	STEP	Description of NC Section A	Corrective Action Secondarial Action Description		ction B	on B Sign &		cation	Approval Chief Eng	Approval QC Inspector			
		Occilon A	Chief Eng	Chief Eng		Date	Secti		Office Eng	QO Mapector			
					-								
		****											
							}						
					,								
·													
					İ								




Dart	Aer	ospa	ce	Ltd
------	-----	------	----	-----

W/O:		WORK ORDER CHANGES											
DATE STEP		PRO	OCEDURE CHA	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
								1 Tod Wigi					
				1,000									
Part No: PAR #:		Fault Cate	Fault Category: NCR: Yes No			No DQA: Date:							
	Resolution: Disposition: QA: N					N/C Closed: Date:							
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCR	)	,						
DATE	STED	Description of NC		Corrective Action Section		Verific	cation	Approval	Approval				
DAIL	DATE STEP Description of NC Section A	Initial Chief Eng	Action Description  Chief Eng	Sign & Date	Secti	on C	Chief Eng	QC Inspector					
						,							



Dart	Aeros	pace	Ltd
------	-------	------	-----

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
*													
·													
Part No:		PAR #:	Fault Cate	egory:	_ NCR: Yes N	lo DQA:	Date:						
Resolution:		Dispositi	on:	_ QA: N/C Clo	Date:								
NCR:		V	WORK ORE	DER NON-CONFORMA	NCE (NCR)								
DATE	STEP	Description of NC	Corrective Action Section			Verification	Approval	Approval					
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector					
						i.							
<u></u>				·····									
						,							
						,		·					
,													



Dart Ae	rospace	Ltd								'yda-
W/O:			W	ORK ORDER CHA	NGES					
DATE	STEP	PRO	OCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
				,						}
Part No: PAR #:		Fault Category: NCF			CR: Yes No DQA:			_ Date: _		
	Re	esolution:	Disposition: Q			QA: N/C Closed: Date: _				
NCR:		V	VORK ORD	ER NON-CONFOR	RMANCE	(NCR	)			
DATE	0750	Description of NC	Corrective Action Section			Veri		ication	Approval	Approval
DATE	STEP	Section A				Chief Eng	QC Inspector			
									,	